

# **Confidential Report**

Our Ref: 23/59588A/04/22





1066



Client:

Wira House, West Park Ring Road, Leeds, LS16 6QL, UK.

Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

Date: 27 April 2022

Our Ref: 23/59588A/04/22 Your Ref: F-PCP-43-2

Page: 1 of 4

Kobefab International B.V.

De Vest 62

5555 XP Valkenswaard

Neterlands

Job Title: Fire Test on One Fabric Sample

Clients Order Ref: F-PCP-43-2

Date of Receipt: 19 April 2022

Date Test Started: 26 April 2022

Description of Sample: One sample of fabric, which was referenced by the client as;

Project Number: 2201. Kobe Name: Amarant FR . Stated to be 96% PES 4% Vi.

Work Requested: We were asked to make the following fire test:

BS 5852: Clause 11:2006 (2011)

- \* subcontracted test, UKAS accredited
- \*\* subcontracted test, EN ISO/IEC 17025 accredited
- \*\*\* not UKAS accredited

Note: This report relates only to the samples submitted and as described in the report.









Wira House, West Park Ring Road, Leeds, LS16 6QL, UK.

Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

Date: 27 April 2022

Our Ref: 23/59588A/04/22 Your Ref: F-PCP-43-2

Page: 2 of 4

Client: Kobefab International B.V.

Testing BS 5852: Clause 11: 2006 (2011) Assessment of the ignitability of upholstered seating by Smouldering and Flaming sources – Source 5 (Crib 5)

#### **Pre-Treatment**

The material was subjected to the water soak procedure according to BS 5852:Annex E:2006 (2011).

# **Conditioning**

The sample was conditioned and tested in the environments specified in Clause 10 of BS 5852: 2006 (2011).

# **Testing**

The material was tested according to BS 5852:2006 (2011) Methods of test for the ignitability of upholstered composites for seating by flaming sources using Source 5 (Crib 5).

The sample was tested at 19°C and 38% relative humidity (R.H.).

The sample was tested over combustion modified polyurethane foam with a density of approximately 35-36kg/m<sup>3</sup>.







Wira House, West Park Ring Road, Leeds, LS16 6QL, UK.

Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

27 April 2022 Date:

Our Ref: 23/59588A/04/22 Your Ref: F-PCP-43-2

> Page: 3 of 4

**Client:** Kobefab International B.V.

### **Results**

The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use.

	Specimen 1	Specimen 2
Time of Ignition (s)	21	17
Time of Flame Extinction (s)	211	238
Time of Smoke Extinction (s)	418	391
Time of cover split	30	38
Extent of damage (mm) - Seat		
Width	104	99
Length	82	93
Depth	46	37
Extent of damage (mm) - Back		
Width	107	94
Length	351	373
Depth	42	55
Melting	Yes	Yes
Dripping	No	No
Charring	Yes	Yes
Comments and Observations		
Specimen Result (Ignition or Non-ignition)	Non-Ignition	Non-Ignition

#### Acronyms

ME – Manually extinguished DNO – Did not observe time of events EC – Escalating combustion BTT – Burnt through thickness of foam DNS - Material did not split BTE - Burnt to extremities







Wira House, West Park Ring Road, Leeds, LS16 6QL, UK.

Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

Date: 27 April 2022

Our Ref: 23/59588A/04/22 Your Ref: F-PCP-43-2

> 4 of 4 Page:

**Client:** Kobefab International B.V.

#### Comment

The results indicate 'Non-Ignition' of the materials and the test is designated NI/5 (ie. Pass).

An estimation of uncertainty of measurement has been taken into account when making a judgment to any pass/fail criteria. Under our Policy we have used a non-binary decision rule.

See our Decision rules Policy (http://www.bttg.co.uk/decision-rules-policy) for further information.

# **Uncertainty Budget**

Measurements: ± 2 mm Timings: ± 2 seconds

...... B Bland, Technical Customer Services Officer Reported by:.....

Countersigned by:... ..... P Doherty, Manager

Enquiries concerning this report should be addressed to Customer Services.



